



FAUX LEATHER PATCHES

 MEDIUM PRESSURE

1. PREHEAT HAT

*OR OTHER NON-LAUNDERED ITEMS

 10 SECONDS

2. PRESS PATCH

DUAL

 280° TOP 320° BOTTOM  45 SECONDS

SINGLE

 320°  45 SECONDS